Work Orde	e <b>r ID 57694</b> :01:11 PM	SCRETT IIIII IIII IIII IIII IIII IIII IIII									Page 1
tem ID: Revision ID:	D6005-128		Accept					Setup	Start		
	Crosstube Material								Stop		
Start Date:  Required Date: 4  Reference:	4/13/10 Start Qty: 1.00 4/14/10 Req'd Qty: 1.00		Tooling: SPC (Y/N):	Cust Item ID: Customer:  Date: Date:				٠			
Approvals:	Process Plan: QC:	Date:						Run	Start Stop		
Sequence ID/ Work Center ID	Operation Description	3	Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	t Rej Qty		Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr				1.	- + -					<del></del>
D6005	Rev A										
55 Crosstubes	Memo	,	0.00			· .	a.M		10 -	04	-270
Crosstubes											
60 	QC21- Final Inspection	0.00		10/04/30							
QC Quality Control	Memo		0.00					4	·	) · · · · · /· (	

W 10006.29

April 13, 2010 3:01:10 PM

Work Order ID: 57694

Parent Item:

D6005-128

Parent Item Name:

Component Item ID/

Crosstube Material

Comments:

Item Name

D6005-128

IPP Rev:C□04.06.15□Added tolerance to Step 2□KJ/JLM

IPP Rev:D 08-09-23 fixe typo in dwg name DD verified by:EC

Item ID

Replacement Mfg/ Purch Manufactured Bin Primary Item Location No

Location

Last

Route Seq ID Unit of Measure

Qty on Hand

Remaining Qty To Pick Issued

**Start Date: 4/13/10** 

Start Qty: 1.00

Date Status Issued

Each

26.0000

1.0000

Crosstube Material

Warehouse

Location

Main Warehouse

LG

53593

Loc Qty

Loc Code

10-4-28 (I)

Qty

Required Date: 4/14/10

Required Qty: 1.00

26